


































120 min






A




A	B_(mm)	C_(mm)	D_(mm)	E	F
A01	1502	380	16	1	2 2
A02	1502	380	16	1	2 2
A03	764	380	16	1	2 2
A04	764	380	16	1	2 2
A05	764	360	16	1	2 2
A06	764	360	16	1	2 2
A10	476	350	16	2	1 2
A31	774	491	3	2	1 2
A32	774	496	3	1	1 2
A40	792	496	16	2	1 2
AD1	454	353	3	4	1 2
AS1	496	195	16	2	1 2
AS2	496	195	16	2	1 2
AT1	444	81	16	4	1 2
WQ1	350	96	12	4	1 2
WQ2	350	96	12	4	1 2

1




2




x8

A02

2



1



x4

9



ø15

x2





54











ø35

x2









A03











3





4







5



6








x2







7




x4



8




x4




9

AS1/AS2






x4




10



A=B




x4




AD1








11







12



13




14




15

A=B



35



x14

38






x16

39



3x20

x30



16

4A

4x16









x1

41







x1

80




x1












17






18














19













XXXXXXXXXX
.....
serie: xxx
.....
Hergestellt fur:
.....
.....






60 min






J








A	B_(mm)	C_(mm)	D_(mm)	E	F
J01	1068	598	16	1	1 1
J02	1101	602	16	1	1 1
J03	378	600	16	1	1 1
J04	378	600	16	1	1 1
J05	530	361	16	1	1 1



1




2






3

- | | | |
|---|--|---|
| 1  x2 | 2  x3 | 9  $\varnothing 15$ x2 |
|---|--|---|




4


- | | | |
|--|---|--|
| 1  x2 | 2  x3 | 9  $\varnothing 15$ x2 |
|--|---|--|





5






6







7









8




9










A







A	B_(mm)	C_(mm)	D_(mm)	E	3/4
A01	1802	380	16	1	3/4
A02	1802	380	16	1	3/4
A03	196	380	16	1	3/4
A04	196	380	16	1	3/4
A05	196	360	16	1	3/4
A06	196	360	16	1	3/4
A30	206	589	3	2	3/4
A31	206	600	3	1	3/4
A40	596	224	16	2	3/4
AD1	554	353	3	1	3/4
AS1	596	224	16	1	3/4
AT1	544	81	16	1	3/4
WQ1	350	96	12	1	3/4
WQ2	350	96	12	1	3/4




1






2





3




4






5

- 1**  x4
- 9**  ø15 x2
- 45**  6,3x13 x2
- 92A**  x1




6

- 1**  x4
- 9**  ø15 x2
- 45**  6,3x13 x2
- 92B**  x1




7

6





5x11
x8

54






ø35
x4




A40

x2



8


2




x2





2











AS1





2








9






10




11







12



13




14



15

A=B

35



x2

38




x14

39




3x20


x16



1.




2.



16


4A

4x16






x6












10













x6
















17






18








19








A	B_(mm)	C_(mm)	D_(mm)	E	F
L03	1426	334	16	2	4 4
L21	468	314	16	2	4 4
L22	468	302	16	2	4 4
L30	1420	478	3	1	4 4
L41	496	366	16	1	4 4
L42	496	366	16	1	4 4
L50	750	462	4	1	4 4
L55	461	300	5	2	4 4




1



2






3








x2

L03




4



5

6

5x11




x4

54



ø35



x2



54

L42


54



6


4A

4x16




x6

36



x6



54

54

36

36

L50





36

36


36




54

54




7

9A  x16









8








9









A=B






10











11




12



13






P











A	B_(mm)	C_(mm)	D_(mm)	E	F
P01	1002	334	16	1	1 4
P02	1002	334	16	1	1 4
P03	1394	334	16	1	1 4
P04	1394	334	16	1	1 4
P05	1394	314	16	1	2 4
P10	476	300	16	2	1 4
P20	476	314	16	4	1 4
P31	1404	489	3	1	2 4
P32	1404	489	3	1	2 4
P41	682	496	16	2	2 4
P42	496	366	16	2	2 4
P43	366	496	16	2	2 4



1




2




3








- 1**  x4
- 54**  $\varnothing 35$ x6
- 9**  $\varnothing 15$ x2
- 2**  x4







4

- 9**  $\varnothing 15$ x16







6






P41

x2







7

x2







P42




8



- 6** 5x11
x8
- 54** ø35
x4




9






- 9A** x8




10




9A  x8




11

22  x6





22A  x6




12






13




14

9A  x6




15




35  x13

38  x16










39  3x20 x29






A=B












16






17



18














N







A	B (mm)	C (mm)	D (mm)	E	F
N01	1800	195	16	1	3 4
N02	1800	195	16	1	3 4

1




OPTION



2

80



x3

